

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection: Company Mike W. Glasson Environmental Coordinator OGM Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0150032	
Inspection Type:	PARTIAL	
Inspection Date:	Wednesday, October 04, 2006	
Start Date/Time:	10/4/2006 9:00:00 AM	
End Date/Time:	10/4/2006 11:00:00 AM	
Last Inspection:	Monday, September 18, 2006	

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Cloudy/Overcast, Temp. 57 Deg. F.

InspectionID Report Number: 1101

Accepted by: pgrubaug

10/26/2006

Permitee: GENWAL RESOURCES INC
Operator: GENWAL RESOURCES INC
Site: CRANDALL CANYON MINE

Address: PO BOX 1077, PRICE UT 84501

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

С	ur	rent	Ac	rea	ges

Total Permitte	6,235.80
Total Disturbe	10.70
Phase I	
Phase II	
Phase III	

Mineral Ownership Types of Operations

✓ Federal	Underground
State	Surface
☐ County	☐ Loadout
Fee	Processing
Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

A midterm review of the Crandall Canyon Mine Permit C/015/0032 is currently in progress.

A Bond review is in progress.

Inspector's Signature:

Karl R. Lousluper

Date

Wednesday, October 04, 2006

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Wednesday, October 04, 2006

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		\checkmark	
2.	Signs and Markers	✓		V	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		✓	✓
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓			
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	V			
6.	Disposal of Excess Spoil, Fills, Benches	✓	✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓	✓		
8.	Noncoal Waste	~		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Wednesday, October 04, 2006

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

A midterm review of the Crandall Canyon Mine Permit C/015/0032 is currently in progress.

A Bond review is in progress.

2. Signs and Markers

A new Mine ID sign has been installed.

The Mine ID sign is posted at the entrance to the permit area from the forest service road. The sign contains the name, permit ID #, address, and phone number of the operator. All other signs and markers observed during the inspection met the coal rules.

4.a Hydrologic Balance: Diversions

The disturbed inlet located on the coal storage pile is 100% plugged. Violation #10001was issued for failure to maintain. The location is within the disturbed area, no off-site impact.

The culvert inlet by the noncoal waste storage bin is about 50% plugged and the culvert outlet by the warehouse is about 50% plugged. All three locations need maintenance work.

4.d Hydrologic Balance: Water Monitoring

Second quarter 2006 water monitoring information is in the EDI website and uploaded.

8. Noncoal Waste

Several items of noncoal waste were inside of the diversion from the noncoal storage area to the oil storage area. Mike Glasson made arrangements to have these items picked up during the course of the inspection.